

CUMBRIAN RAILWAYS ASSOCIATION PHOTO LIBRARY - PEARSALL COLLECTION: North Western Railway between Lancaster and Wennington

Neg No	Location	Description	Date	Quality
A59/19-4	Low Weaning Bridge	Side view of bridge	19590403	A
A60/34-1	Eldroth ?	LMS 5MT 4-6-0 44775, down passr	19600929	A
A60/34-2	Eldroth	LMS 5MT Crab 2-6-0 42895 2-53 Leeds-Morecambe parcels	19600929	A
A60/40-2	Laneside	BR 4MT 2-6-0 76051 12-30 Morecambe-Leeds passr	19601114	A
A60/40-3	Laneside	BR CI 40 D258 12-50 Lancaster-Stourton empties, goods, no headcode panels, no yellow panel	19601114	A
A60/40-4	Laneside	LMS 8F 2-8-0 48283 12-40 Carnforth-Skipton goods	19601114	A
A60/40-5	Laneside	LMS 4F 0-6-0 41222 12-50 Heysham Moss Sidings-Stourton tanks	19601114	A
A62/02-4	Farleton No.2 Crossing	Crossing keeper's cottage	19620423	A
A62/02-5	Caton, nr	LMS 4F 0-6-0 44467, Otley ?-Morecambe excursion	19620423	B
A63/21-8	Farleton Crossing	LMS 5MT 4-6-0 45455 2-46 Morecambe-Leeds passr	19630731	A
A63/22-7	Farleton Crossing	LMS 4F 0-6-0 44467 2-46 Skipton-Lancaster goods passes distant signal	19630731	A
A63/22-8	Farleton Crossing	LMS 4MT Fowler 2-6-4T 42322 1-53 Leeds-Morecambe passr on crossing	19630731	A
A64/02-7	Crook of Lune viaduct	BR 5MT 4-6-0 73163 down Morecambe excursion comes onto viaduct	19640303	A

A64/02-8	Crook of Lune viaduct	BR CI 45 D15 9-33 Morecambe-Leeds passr on viaduct	19640303	A
A64/03-1	Caton, nr	BR 7MT Britannia 4-6-2, down passr alongside road	1964	A
A64/03-2	Caton, nr	BR CI 25 D7568 8-30 Bradford-Morecambe passr 2M73	19640330	A
PED183	Hornby station	General view of station lkg E	nd	A
PEF406	Crook of Lune viaduct	LMS 4MT 2-6-0 43113 2-10 Morecambe-Leeds excursion	19520913	A
PEF407	Crook of Lune, nr	LMS 4F 0-6-0 44501 2-25 Morecambe- passr	19520913	A
PEF408	Crook of Lune viaduct	Viaduct (bridge No. 123) viewed from river level	19520913	A
PEF409	Crook of Lune viaduct	LMS 4P Compound 4-4-0 41139 2-45 Morecambe-Leeds, on viaduct, viewed from lineside	19520913	A
PEF410	Crook of Lune, nr	LMS 4MT 2-6-0 43034 3--0 Heysham-Leeds goods	19520913	A
PEF411	Caton, nr	MR 3F 0-6-0 43293 Clapham-Lancaster pickup goods	19520913	A
PEF412	Caton, nr ?	LMS 4P Compound 4-4-0 41196, down passr	19521221	A
PEF928	Caton station	General view lkg E through station, from up platform	19541002	A
PEF929	Caton	LMS 4MT 2-6-0 43113 + LMS 5MT 44746 Caprotti 2-46 Morecambe-Leeds pasr	19541002	#
PEF930	Caton	LMS 5MT Crab 2-6-0 42771 Leeds/Bradford-Morecambe excursion	19541002	A
PEF956	Caton, nr	LMS 8F 2-8-0 48005 down tanks, snow cover	19550118	A
PEF957	Claughton Manor	LMS 5MT Crab 2-6-0 42810 8-33 Bradford-Morecambe passr, snow cover	195501	A

			18	
PEF958	Claughton Manor	LMS 8F 2-8-0 48616, down goods, snow cover	195501 18	A
PEF959	Claughton Manor ?	LMS 8F 2-8-0 48105, down goods, snow cover	195501 18	A
PEI334	Caton, nr	BR CI 101 dmu 2-45 Morecambe-Leeds	196505 ?	A
PEI335	Caton, nr	LMS 5MT 4-6-0 44888 ? 2-55 Heysham-Stourton goods on occupation crossing; MR distant on rt	196505 ?	A
PEI629	Crook of Lune viaduct	Track lifting in progress, rails being loaded onto train on down line	196807	A
PEI662	Crook of Lune viaduct	General view of viaduct	196808 14	B
PEJ340	Halton, nr	LMS 6P Jubilee 4-6-0 45619 12-43 Bradford-Morecambe passr	195511 12	B
PEJ341	Halton	LMS 2P 4-4-0 40409 + LMS 4P Compound 4-4-0 41045 2-46 Morecambe-Leeds passr	195511 12	A
PEJ403	Wennington W of	LMS 5MT 4-6-0 44858 Heckmondwyke-Morecambe excursion	195604 02	A
PEJ810	Halton, nr	LMS 4F 0-6-0 44306 2-16 Morecambe-Leeds passr W567	195706 11	A
PEJ811	Halton, nr	LMS 6P Patriot 4-6-0 45542 2-25 Morecambe-Bradford passr	195706 11	A
PEJ812	Halton, nr	LMS 4F 0-6-0 43893 down ecs special M572	195706 11	A
PEJ821	Hornby station	General view lkg W	195706 13	A
PEJ822	Hornby, nr	LMS 4P Compound 4-4-0 41196 2-46 Moecambe-Leeds passr, Hornby down home on left	195706 13	A
PEJ892	Wennington	LMS 5MT 4-6-0 44827 11-30 Morecambe-Sheffield passr leaves	195708	A

			24	
PEJ893	Wennington	LMS 4F 0-6-0 43893 11-20 Skipton-Morecambe passr approaches	195708 24	A
PEJ894	Wennington	LMS 4P Compound 4-4-0 41060 10-45 So Leeds-Carnforth passr approaches	195708 24	A
PEK219	not known	LMS 5MT 4-6-0 44649, passr -Q-	195804 12	A
PEK221	Wennington, W of	LMS 5MT 2-6-0 42950, fitted goods	195804 12	A
PEK222	Wennington, W of	LMS 5MT 4-6-0 44683. Passr	195804 12	A
PEZ928	Caton Crossing	Crossing keeper's house by line, crossing removed	196704 05	B
PEZ929	Farleton No.2 Crossing	View lkg E along tracks with crossing keeper's cottage	196704 05	A
PEZ930	Farleton No.2 Crossing	Crossing keeper's cottage	196704 05	A
PEZ931	Farleton No.2 Crossing	BR 9F 2-10-0 92080 10-50 Morecambe-Manvers Main empties passing MR-type distant signal	196704 05	A
PEZ932	Cloughton Crossing	Crossing keeper's cottage and crossing	196704 05	A

Notes: Dates are in order of yyyyymmdd

C suffix indicates colour image

Quality assessment is very subjective, mainly based on image quality, but also in historic interest if image is not top quality

PWR